


# CASE STUDY: PIGEON NETTING



BEFORE VS AFTER



## THE CHALLENGE

A warehouse loading bay was experiencing persistent pigeon nesting issues, creating unsanitary conditions and potential operational hazards.

## THE SOLUTION

Expert Bird Control installed bird netting across three canopies (12m x 8m each), selecting PestFix for its reliability, customer service, and prompt delivery. The installation utilised PestFix's:

- Pigeon netting
- Wire rope and strainers
- Staples and fixings

## THE RESULT

With extensive experience in bird control, the installation was carried out smoothly and successfully. The netting created a 100% effective barrier, completely eliminating the pigeon infestation and keeping the loading bay bird-free. Expert Bird Control expressed high satisfaction with the quality of PestFix's netting and the service provided. The company would confidently recommend PestFix products to other installers and businesses seeking effective bird control solutions.

## GET IN TOUCH

Contact us today for a reliable and effective bird control solution tailored to your needs.

 [www.pestfix.co.uk](http://www.pestfix.co.uk)

 [sales@pestfix.co.uk](mailto:sales@pestfix.co.uk)

 01903 538 488